

CASE STUDY

Rectification Coverage Brings Construction Claim to Resolution

Property & Casualty

Company Profile:

INDUSTRY
Construction

REVENUE
\$50M

LOCATIONS
Four U.S. Locations



Request

A prominent civil contractor was replacing a highway sound wall. This sound wall project included setting large concrete posts. During the drilling, the contractor discovered that the drill line was off by two feet and needed to be adjusted.



Solution

Brown & Brown had recently placed professional liability for this customer, including rectification (also known as “rip & tear”) coverage. This coverage enables a problem to be fixed before it becomes a bigger problem.



Results

Since the new coverage was already in place, the Brown & Brown team submitted the cost to fix the issue, and the insurer paid the damage under the rectification coverage.



How Brown & Brown Can Help

Connect with our Brown & Brown team to learn about our knowledge in your industry, how we build our risk mitigation strategies and how we can aid your business in building a cost-saving property & casualty program.



Find Your Solution at [BBrown.com](https://www.brownandbrown.com)

Brown & Brown, Inc. and all its affiliates, do not provide legal, regulatory or tax guidance, or advice. If legal advice counsel or representation is needed, the services of a legal professional should be sought. The information in this document is intended to provide a general overview of the topics and services contained herein. Brown & Brown, Inc. and all its affiliates, make no representation or warranty as to the accuracy or completeness of the document and undertakes no obligation to update or revise the document based upon new information or future changes.

©2023 Brown & Brown. All rights reserved.